Oasis Service Report 2010
Version 3.02.xx

Major Issues Addressed

Oasis - Major Issues Addressed

- Various Sequencer issues (e.g. lead-lag).
- Default data corrected on inputs page 2.
- Recall now calls "Dynamic Backup" phase.
- Advance walk is now compatible with coordination.
- Various Red Rest Issues
- Master/Internal local issues.

Oasis - Major Issues Addressed

- Overlap – Red clearance skip issue.
  - Only occurs in highly rare cases.
- DST adjustment when connected to GPS.
  - Spring adjustment
- WDT fault generated when D-6 menu accessed.
  - Related to Data Key dynamic displays.

Oasis - Major Issues Addressed

- Overlap clearance when transitioning into preempt.
  - Only occurs when "yellow clear before preempt" interval is set lower than normal phase "yellow clearance" interval.
- Hardware Failure No. 9 tolerance widened.

Oasis – Major Issues Addressed

- Master Clock and Local Clock Drift
- Lead / Lag skip in coordination

Oasis Service Report 2010 Version 3.02.xx

Enhancements

Oasis - Enhancements

- Stop time will now pause the "pedestrian clearance" timer.
- New Status displays
  - Alarms – 24 most recent
  - Events – 24 most recent
- Added upload capability for Oasis version.
- Added average speed calculation.

Oasis - Enhancements

- Added "on-off" transition logging capability for "special function" alarm inputs.
- Refresh rate of all inputs and outputs stabilized to help with WDT faults.

Contract Runs until July 2015